Key: G - Good A - Average P - Poor



Advanced Inspection: Combine

Inspector:	Make:Case IH	
Date Inspected:Dec 16, 2013	Model:2188	
Prepared For:	Serial Number:	
Location: Alexandria, MN	Hours Shown:4000E/3000S	
Brief Description:		
2188 combine with 30.5 singles, RWA, field tracker, rock	trap, chopper, specialty rotor, and grain tank extensions.	
G A P N/A ENGINE	Inspector Notes	
Engine Oil Level and Condition	Engine oil level slightly low	
Coolant Level and Condition		
Radiator, Cap, Hoses, and Connections		
☐ ■ ☐ Fuel System		
☐ ■ ☐ Air Intake/Filter		
☐ ■ ☐ Manifold, Muffler, and Exhaust Systems		
Fan and Belt Condition	Fan bent	
☐ ■ ☐ Water Pump Condition		
Exhaust Smoke		
Unusual Noise		
☐ ☐ ☐ High/Low Idle Speed		
☐ ☐ Turbo Inspection		
G A P N/A TRANSMISSION AND DRIVE SYSTEM	Inspector Notes	
☐ ☐ ☐ Transmission Oil Level, Filter, and Condition		
☐ ☐ ☐ Final Drive Fluid Levels and Condition		
■ ☐ Proper Shifting		
☐ ☐ ☐ Drive Test		
Parking Brake Operation		
Axle/Drive Condition		
☐ ☐ ☐ Wheel Bearing/Seals		

G	Α	P N/A	TRANSMISSION AND DRIVE SYSTEM	Inspector Notes
			Brake Condition	
			Clutch Operation	
			Rear Wheel Assist Condition	
			Presence of Oil Leaks	
			Visual Rim and Hardware Inspection	
			Tire Condition	Front tires 60%; rear tires 20%
			Differential Lock Operation	
			Steering Operation	
			Steering System Visual Inspection	
			Hydro Condition	Worn splines; pulley bearing needs to be replaced
G	Α	P N/A	HYDRAULIC SYSTEM	Inspector Notes
			Pump Condition	New
			Hose Condition	
			Tank/Reservoir Condition	
			Valves	
			Leaks	
_				
G	A	P N/A	-	Inspector Notes
			Battery and Cable Visual Inspection	
			Starter Operation	
			Charging Operation	
			Heat and A/C Function	
			Field and Road Lights	head light, tail light, and flasher lights need to be replaced
			Turn Signals	
			Instrumentation and Warning Lights	E1 header fault code
			Wipers and Washers	
G	Α	P N/A	MISCELLANEOUS	Inspector Notes
			Cab Condition	
			Seat Operations and Condition	
			Radio Operation	
			Exterior Condition	Some dents
			Paint Condition	Some Rust
			ROPS Visual Inspecton	
			Decals Intact	One torn
			Shields Intact	Missing clean fan shield and spreader belt shield
	_			

G	Α	Р	N/A	TRACKS	Inspector Notes
				Track Condition	
				Track Alignment	
				Roller Oil Leaks	
				Drive Wheel Condition	
				Bogie Wheel Condition	
				Idler Wheel Condition	
				Undercarriage Condition	
G	Α	Р	N/A	FEEDERHOUSE	Inspector Notes
				Feederhouse Drum Condition	
				Feederhouse Chain Condition	
				Feederhouse Sprockets and Bearings	replace sprocket
				Rock Beater Shaft Bearings	replace bearing
				Drive Belt	
				Feederhouse Floor Condition	some small dents
				Lateral Tilt Condition	cracks, missing poly
				Feederhouse Run Test	
G	Α	Р	N/A	THRESHING SYSTEM	Inspector Notes
				Belts	Rotor belt cracked
				Chains	
				Bearings	
				Drive System	
				Rotor/Cylinder	
				Hardware	
				Concaves	Some damage
				Cage	Bent
				Cone Condition	
				Threshing System Run Test	
					<u> </u>
G	Α	Р	N/A	CLEANING SYSTEM	Inspector Notes
				Belts	
				Chains	worn
				Bearings	
				Fan Condition	
				Sieve Condition	top and bottom damaged, out of alignment, welded plate (see pic)
				Elevator Chain Condition	
				Auger Bed or Pan Condition	auger bed blocks

G	Α	P N/A	CHOPPING SYSTEM	Inspector Notes
		■ Belts		
		■ Chopper		Blade dull
		Bearings		
		Pan		Bent
		■ Hardware		
G	Α	P N/A	SPREADING SYSTEM	Inspector Notes
		☐ ☐ Belts		
		☐ Chains		
		Bearings		
		Paddles		
		Other		Gears worn
П				
	_			- · ·
G	A	P N/A	UNLOAD SYSTEM	Inspector Notes
<u>G</u>	A ■	P N/A Belts	UNLOAD SYSTEM	Inspector Notes
G	_		UNLOAD SYSTEM	Inspector Notes
G		Belts	UNLOAD SYSTEM	Inspector Notes
G		Belts Chains	UNLOAD SYSTEM	Inspector Notes
G		Belts Chains Bearings Auger Hopper		Inspector Notes
G		Belts Chains Bearings Auger		Inspector Notes
G		Belts Chains Bearings Auger Hopper		Inspector Notes
G		Belts Chains Bearings Auger Hopper		Inspector Notes Inspector Comments
		Belts Chains Bearings Auger Hopper Unload Rui	n Test	Inspector Comments Overall combine is in average condition. Starts and runs very well.
 	A	Belts Chains Bearings Auger Hopper Unload Rui	n Test ing	Inspector Comments